

# Release Notes

## Version 3.6.1 (the latest)

- Fixed inability to set UNC-style path (\\Server\Folder).

## Version 3.6 (Sep'19)

- Greatly improved performance (~400%) of image sequence export (JPEG/TIFF/PNG), by switching from FFPMEG to the new internal engine;
- Fixed crash in configuration editor in Linux version;
- Fixed inability to select storage path if currently set path doesn't exit.

## Version 3.5.1

- Fixed random dropped frames issue during the export to slow storage.

## Version 3.5 (July'19)

- Added camera rename functionality;
- Fixed the crash in the Control App when run on touchscreen devices;
- Fixed initialization of CIS cameras (broken in last release).

## Version 3.4.2

- Fixed crash during playback on multi recorder systems;
- Fixed crash during playback of recording with different camera configuration than the current one;
- Improved camera switch speed during playback.

### Version 3.4 (May'19)

- Added high precision (>8-bit) export;
- Added TIFF export;
- Improved export speed;
- Fixed incorrect image rendering on certain color low resolution cameras;

### Version 3.3.1

- Fixed recording drive access right issue on certain Windows installations.

### Version 3.3 (April)

- Added new fault tolerance option to set the behavior of how faulty cameras are treated;
- Added support for VisionResearch and Vieworks cameras;
- Fixed licensing issue when server were losing license when run for several days;
- Other minor fixes and improvements.

### Version 3.2 (Dec'18)

- Added support for eBus runtime to support generic USB/GigE cameras;
- Released plugin SDK for online and offline processing of captured data;
- New camera selection mechanism for live preview streams;
- Fixed initialization issue for Adimec cameras;
- Other minor fixes and improvements.

### Version 3.1.5

- Fixed network connection issues on certain systems with Hyper-V NAT;
- Fixed random hang issue with certain USB/GigE cameras.

## Version 3.1 (Nov'18)

- Added support for IDS and IOIndustries Victorem series cameras;
- Moved camera synchronization mode selection to the UI from config file;
- Added network card selection to configuration app;
- Other minor fixes and improvements.

### International Distributors

---



Sky Blue Microsystems GmbH  
Geisenhausenerstr. 18  
81379 Munich, Germany  
+49 89 780 2970, [info@skyblue.de](mailto:info@skyblue.de)  
[www.skyblue.de](http://www.skyblue.de)



In Great Britain:  
[Zerif Technologies Ltd.](http://ZerifTechnologiesLtd.com)  
Winnington House, 2 Woodberry Grove  
Finchley, London N12 0DR  
+44 115 855 7883, [info@zerif.co.uk](mailto:info@zerif.co.uk)  
[www.zerif.co.uk](http://www.zerif.co.uk)